PCC Plan

Chempro, Pier 91

Attachment 1

Monthly inspection Report

OK

Needs Repair

I. Containment:

- 1. Berms appear structurally sound.
- 2. Oil or water accumulations with a berm.
- 3. Vegetation or rubbish accumulations.
- Operation of sump and separator satisfactory.

Commer	t on	repair	needed	Associated materials a considerable for the respective of the substitution of the substitution of the	

II. Tanks:



Needs Repair

- 1. Teakage at seams, or access covers.
- P Evidence of overflow.
- Rust or corrosion at base, on exterior.
- 4. Foundations settling or cracking.

Commen	on	repair	needed		
--------	----	--------	--------	--	--

III. Welves, Pipes and Pumps:



Needs Repair

- Leakage at fittings and glands.
- 2. Proper operation of valves and pumps.
- 3. Rust and corrosion.
- Pipe supports for damage or abrasion.

USEPA RCRA

3012687

Page 19

Montaly Inspection Report (cont'd)

Comments on repairs needed

IV. Loading/Unloading Area

OK

Needs Repair

- 1. Evidence of leakage or spills.
- 2. Rust and corrosion.
- 3. Damaged or missing equipment.
- 4. Drip buckets available.

Comments on repairs needed

V. Security



Needs Repair

- Proper operation of facility security lighting.
- Rubbish or vegetation that would reduce overall visibility within the facility.
- VI. Facility and Personnel General
 - 1. Secc Plan is on file.
 - SPCC Plan reviewed with personnel within past three (3) months.
 - 3. Plant personnel are properly trained in the operation and maintenance of equipment.
 - 4. Plant personnel are properly trained in the use of spill prevention equipment.
 - 5. Plant personnel clearly understand spill reporting procedures.
 - 6. Fire extinguishers fully charged and inspected within past 12 months.
 - 7. Oil cleanup materials available.

Monthly Inspection Report (cont'd):

- VI. Facility and Personnel General (cont't)
 - 8. No obvious fire hazards.
 - All oily residue cleaned from valves, pipes, tanks, steps, tadders and ground surfaces.
 - 10. Storage of parts, equipment and materials neat and orderly.

 Comments on repair needed ok

DATE: 4-1-86

SIGNED: Nata Mathur

NOTE: This report is to be maintained in file for a minimum of three (3) years.